Certificate of Testing

Issued By:

CULP FABRIC CENTER

2742-A Tucker Street Extension Burlington, NC 27215 (336) 229-2562

The following listed pattern is in compliance with TB 117-2013 regulations. Under TB 117-2013 the fabric must meet all three of the following requirements to be considered a "Pass"- 1. The vertical char cannot exceed 45 mm or $< 1 \frac{3}{4}$ ", 2. The test specimens cannot smolder more than 45 minutes and 3. The test specimen cannot transition into an open flame.

Connelly	Pass
Pattern:	Actual Results

Date: 04/09/2018

Quality Assurance Manager

Culp, Inc.