≣ ≡ ≣ Ⅲ CULP

Certificate of Testing

ISSUED BY **CULP FABRIC CENTER** 2742-A TUCKER STREET EXTENSION BURLINGTON, NC 27215 (336) 229-2562

The following listed pattern have been tested in accordance with California Technical Bulletin 117-2013, Section 1, Cover Fabric Test and meets the requirements of this standard.

Under TB 117-2013 the fabric must meet all three of the following requirements to be considered a "Pass"- 1. The vertical char cannot exceed 45 mm or <1 ³/₄", 2. The test specimens cannot smolder more than 45 minutes and 3. The test specimen cannot transition into an open flame.

		Actual Results		
Pattern	Pass or Fail	Fill/Fill	Warp/Warp	Warp/Fill
Joyful MBF	Pass	13 mm	13 mm	20 mm

Keyah Barksdale

Date: 01/26/24

Keyah Barksdale

CFC

Quality Assurance Manager Culp, Inc.