

CULP

Certificate of Compliance

ISSUED BY

CULP UPHOLSTERY FABRICS

2742-A TUCKER STREET EXTENSION

BURLINGTON, NC 27215

(336) 229-2562

COC 26-029

The following listed pattern have been tested in accordance with California Technical Bulletin 117-2013, Section 1, Cover Fabric Test and meets the requirements of this standard.

Under TB 117-2013 the fabric must meet all three of the following requirements to be considered a "Pass":

1. The vertical char cannot exceed 45 mm or $<1 \frac{3}{4}$ "
2. The test specimens cannot smolder more than 45 minutes
3. The test specimen cannot transition into an open flame.

Pattern	Pass or Fail	Actual Results (mm)		
		Fill/Fill	Warp/Warp	Warp/Fill
Mira YCL	Pass	18	11	20

Keyah Barksdale

Date: 03/05/2026

Keyah Barksdale
Quality Assurance Manager
Culp, Inc.