Certificate of Testing

Issued By:

## CULP FABRIC CENTER 2742-A Tucker Street Extension Burlington, NC 27215

## (336) 229-2562

The following listed pattern is in compliance with TB 117-2013 regulations. Under TB 117-2013 the fabric must meet all three of the following requirements to be considered a "Pass"- 1. The vertical char cannot exceed 45 mm or < 1  $\frac{3}{4}$ ", 2. The test specimens cannot smolder more than 45 minutes and 3. The test specimen cannot transition into an open flame.

> Pattern: Winslow

Actual Results: Pass

Quality Assurance Manager Culp, Inc. Date: 7/8/2014